


BUILDERS & FLYERS
GP4
NEWSLETTER



THE OFFICAL VOICE OF GP-4 BUILDERS ALL OVER THE WORLD

VOLUME 5

NOVEMBER - DECEMBER 1995



BILL BERRICK OF OMAHA, NEBRASKA GP-4 PROJECT


Dear Spud,

I really enjoyed your most recent GP4 Newsletter; the tips from George are sure to be helpful to a lot of builders. I have a number of letters he has written to me in response to various questions along the way. I will be

sending those copies later to be shared in future issues of GP4BFN and it might save George some time in re-writing some things.

I wonder if George meant to say a 4" x 4" x 5' sanding board? A 4" x 4" would be a little heavy;

I used a 1 x 4 x 6 board with two wooden hand holds on the top because it was easier to find a really straight and flat finished board in that dimension. It seemed heavy enough to me; I think George used a 2" x 4".



I very easily could have made a mistake here. They don't call me the "Two Fingered Wonder" for nothing ya know! I did not have George's original letter to confirm my whoops. I'll get the straight scoop from George for the next newsletter. - Spud

I made up an index of the plans early on that saved me a great deal of time during construction. I'll enclose with this letter so we can share it with all the other builders. *Bill's Super index is on pages 3 & 4 of this issue!*

I am just finishing my main gear doors--mounting the outboard metal ones today. The skinning is finished except for the top area between the panel and the firewall. I am leaving that open until the engine is mounted and wired. I'll put the glass bead slurry on the bottoms of the wings and do the finish sanding, hopefully this month, then get about 17 of our EAA Chapter 80 members over again to turn the project right side up. That is how many we used when we inverted it several months ago! This is a walk-out basement with a double door just in front of the fuselage in the photo. We have to carry the wing outside to invert and turn it end for end. I used a cable come-along suspended from the rafters to help lift the center of the main spar until everyone had found a grip on the trailing edge. It was easy enough for that many people, but it made quite a sight for the neighbors--like some giant caterpillar!

Hey Bill! We need a picture next time you have your "caterpillar" out!

So long,

Bill Berrick (402) 292-6832

11803 Hunters Cove

Omaha, NE 68123-1119



			30
Aileron	Fairing	Strips	38
Aileron	Hinge	Detail	25
Aileron	Hinges		27
Aileron	Horn	Location	25
Aileron	Horn	Pattern	27
Aileron	Mass balance	Location	25
Aileron	Plan		25
Aileron	Push rods		38
Aileron	Stops		30
Air	Duct	NASA	53
Air	Intake	Plenum	41
Antennae	Design		8
Battery	Installation		40
Brake	Lines		24
Brake	Lines		34
Brake	Mounting		34
Brake	Parking		6
Bushings	Bolt	Hole	26
Bushings	Through	Spar	39
Bushings	Walking beam		29
Canopy	Base	Layup	47
Canopy	Base	Location	4
Canopy	Bow	Lamination	47
Canopy	Bow	Pattern	46
Canopy	Latch		49
Canopy	Locking pins		46
Canopy	Rail	Material	47
Canopy	Rollers & track		46
Canopy	Track		4
Canopy	Base	Pattern	47
Console	Center	Radio	55
Console	Engine	Control	55
Control	Aileron	Idler arm	32
Control	Aileron	Pushrods	32
Control	Aileron	Pushrods	38
Control	Aileron	Rigging	49
Control	Balance		Man p 12
Control	Console	Engine	55
Control	Cover plates	Stick area	45
Control	Deflection		49
Control	Elevator	Idler arms	9
Control	Elevator	Trim motor	40
Control	Flight	Layout	49
Control	Gear handle	Locking bracket	41
Control	Nosegear	Steering arm	52
Control	Nosegear	Steering truss	51
Control	Pedal	Extension	8
Control	Rudder	Cable pulleys	9
Control	Rudder	Pedals	7
Control	Rudder	Pulley brackets	49
Control	Rudder cable	Guides	45
Control	Rudder cable	Pulleys	48
Control	Stick	Assembly	30
Control	Stick	Cover plates	45
Control	Stick	Detail	29
Control	Stick	Mechanism	28
Control	Stick	Pillow blocks	28
Control	Surface	Travel	49
Control	Trim tab	Detail	13
Control	Trim tab	Pulleys	11
Cowl	Fasteners	Camloc	45

Cowling	Gear	Door	56
Deck Cloth		Man p	33
Electrical	Battery	Installation	40
Electrical	Landing	Light	33
Electrical	Solenoid	Mount	57
Electrical	Tail light	Lens	45
Electrical	Wingtip	Lights	24
Electrical	Wingtip	Lights	48
Electrical	Wiring	Diagram	40
Elevator	Balance	Mass	13
Elevator	Deflection		30
Elevator	Fairing	Detail	11
Elevator	Hinges		13
Elevator	Horn		12, 30
Elevator	Idler Arms		9
Elevator	Plan		13
Elevator	Push-pull	Tubes	9, 30
Elevator	Rib	Patterns	12
Elevator	Stops		29
Elevator	Tips	Foam	13
Elevator	Torque tube		12
Elevator	Trim tab		13
Engine	Air intake	Plenum	41
Engine	Alternate air		57
Engine	Baffles		57
Engine	Exhaust	Hangers	57
Engine	Exhaust		57
Engine	Mount	Brackets	9
Engine	Mount		54
Engine	Oil cooler		57
Engine mount	Thrustline	Offset	54
Fin	Foam	Detail	14
Fin	Mounting	Details	14
Fin	Patterns		14
Fin	Skin	Overhang	15
Firewall			45
Firewall well	Aluminum	Angle	50
Flap	Bell Crank		27
Flap	Cable	Shackle	30
Flap	Cables		32
Flap	Hinge	Location	26
Flap	Hinges & stops		26
Flap	Motor	Assembly	31
Flap	Nose	Fairing	38
Flap	Plan		25
Flap	Pulley	Bracket	32
Flap	Pulleys		32
Fuel	Drain	Valve	6
Fuel	Filler	Drains	23
Fuel	Line	Layout	6
Fuel	Ram air	Vent	24
Fuel	Selector	Valve	35
Fuel	Sight gage		39
Fuel	Sump	Drain	49
Fuel	System		49
Fuel	Tank	Caps	23
Fuel	Tank	Fuselage	6
Fuel	Tank	Wing	23
Fuel	Tank	Pickups	23
Fuselage	Baggage	Frame	4
Fuselage	Compound	Curve	46
Fuselage	Former	Center section	42

Fuselage	Frame	Sideview	5	
Fuselage	Frame		2	
Fuselage	Fuel	Tank	6	
Fuselage	Nose wheel	Tunnel box	54	
Fuselage	Nose wheel	Well	5	
Fuselage	Skin	Overlap	14, 41	
Fuselage	Station	Cross-sections	4	
Gear	Compression	Springs	34	
Gear	Door	Batten	42	
Gear	Door	Brace	33	
Gear	Door	Cowling	56	
Gear	Door	Hinge bracket	44	
Gear	Door	Main	43	
Gear	Door	Mechanisms	44	1/16" cable
Gear	Door	Pulley bracket	44	
Gear	Handle	Downlock mount	5	
Gear	Handle	Locking bracket	41	
Gear	Lights	Micro-switches	37A	
Gear	Main	Layout	32	
Gear	Main	Layout	33	
Gear	Main	Linkage & beam	28	
Gear	Main	Lower leg	34	
Gear	Main	Mounting arms	36	
Gear	Main	Pillow blocks	36	
Gear	Main	Retract assembly	32	
Gear	Main	Retract link	35	
Gear	Main	Scissors	34	
Gear	Main	Sockets	36	
Gear	Main	Spar plate	35	
Gear	Main	Spar plate	36	
Gear	Main		33	3/32" cable
Gear	Nose	Assembly	50	
Gear	Nose	Assist spring	48	
Gear	Nose	Boot	48	
Gear	Nose	Door	42	
Gear	Nose	Doors & lock	56	
Gear	Nose	Pivot plates	5	
Gear	Nose	Pushrod	31	
Gear	Nose	Scissors	49	
Gear	Nose	Steering arm	52	
Gear	Nose	Steering truss	51	
Gear	Nose	Struts	52	
Gear	Nose	Tunnel box	54	
Gear	Nose	Well	5	
Gear	Retract	Assist cables	29	
Gear	Retract	Handle	31	
Gear	Retract	Layout	29	
Gear	Retract	Layout	34	
Gear	Retract	Springs	29	
Gear	Retract	Walking beam	29	
Gear	Retract link	Assembly	36	
Gear	Spring	Layout	33	
Gear	Truss		32	
Gear	Uplock	Air cylinder	37	
Gear	Uplock	Air pump	37A	
Gear	Uplock	System	37	
Gear	Uplock	Valve assembly	37A	
Gear	Retract link	Assembly	35	
Inspection	Hole	Cover	38	
Inspection	Hole	Cover	42	
Instrument	Fuel	Sight gage	39	

GP4BFN 5 PAGE 4

Instrument	Panel		4	
Instrument	Pitot tube		24	
Instrument	Vacuum	System	49	
Lights	Layout		37A	
Painting				Man p 33
Plywood	Layout		53	
Radio	Console		55	
Rudder	Balance	Mass	15	
Rudder	Balance	Mass	16	
Rudder	Cable	Rub plates	Man p 27	
Rudder	Gap	Strips	15	
Rudder	Hinges		16	
Rudder	Plan		16	
Rudder	Rib	Patterns	15	
Rudder	Stops		15	
Scarf	Joints		53	
Seat	Rail	Attachment	32	
Seat	Rail	Cover plates	45	
Seat	Rail	Layout	30	
Seat	Rail	Mounting	31	
Seat	Rail	Inside	29	
Skinning				Man p 4, 10
Spar	Plate		28	
Specifications	General		1	
Spinner	Part number		54	
Stabilizer	Plan		11	
Stabilizer	Position	Detail	14	
Stabilizer	Rib	Patterns	10	
Static	Port	Detail	11	
Tail	Cone	Lens	45	
Tail	Truss		15	
Tail	Cone		45	
Wheel	Well	Clearance	42	
Windshield	Cutting			Man p 26
Windshield	Fairing		41	
Windshield	Mounting		41	
Windshield	Thickness		46	
Wing	Attachment	Fittings	39	
Wing	Center section	Fuselage junct	42	
Wing	Fillets	Top	45	
Wing	Fillets		43	
Wing	Flap & elev ribs	1 thru 10	22	
Wing	Former	Center section	42	
Wing	Fuel	Tanks	23	
Wing	Leading edge	Spar	20	
Wing	Leading edge	Spar	24	
Wing	Nose	Cap	20	
Wing	Nose cap	Template	21	
Wing	Nose ribs	1 to 5	21	
Wing	Nose ribs	6, 7, 10	22	
Wing	Nose ribs	8 & 9	20	
Wing	Plan	Details	24	
Wing	Rib patterns	1 to 3	18	
Wing	Rib patterns	4 to 7	19	
Wing	Rib patterns	8 to 11	20	
Wing	Ribs	Rear 1 & A	37	
Wing	Skin			Man p 38
Wing	Spar	Main	17	
Wing	Spar	Rear	25	
Wing	Tip		48	
Wing	Washout	Jig	38	

GEORGE'S CORNER

Fellow GP-4 Builders:

Our last newsletter asked the question "How can I rip a 3" wide board and get two 2" pieces and a 1" piece?" Obviously you can't as the two saw cuts use up some width. What the builder was really asking can I down size the board some and still use it. There are probably some areas in the fuselage where a slightly smaller width would suffice structurally but I would like to see you builders staying pretty close to all plan dimensions. At least within 1/16" and closer is even better. A lot of structural engineering has gone into areas like the engine mount attach fittings, wing juncture etc. It's important to have a generous area to bolt these very high stress fittings to. Since all of the fuselage lumber is 3/4" thick and milled to this width. A hollow ground blade will rip your beautiful, very expensive spruce with a minimum of waist. It cuts a narrow cut, very smooth, that is ready to glue. Because its hollow ground there is not much set to keep your work from binding. You have to run your board slowly through your power saw. If it starts to bind you can insert a small wedge into the cut in front of the blade to relieve the bind and continue ripping the board. With the spruce I got from Wicks Aircraft Supply I never found a wedge necessary.

The carbide tipped blades last much longer before sharpening is necessary however they make a wider cut. I used 4 hollow ground blades, keeping one or two sharp ones on hand at all times. The sharper the blade the least chance of a bind.

When I gave a material list to Wick Aircraft Supply I thought the structural lumber list was liberal, but would not tolerate any giant mistakes. In the back of the builders manual has a pretty close inventory of your lumber needs.

Substitution: My Osprey II is built out of douglas fir bought from my local lumber yard. Still fly's very nicely! Douglas fir is about 300 psi stronger than spruce however its a little heavier in a strength to weight factor. We found that lumber yards were reluctant to sell their douglas fir to airplane builders. Liability bows its ugly head! I re-engineered the plans in spruce so Osprey II builders would have a quality grade lumber available. If a GP-4 builder needs an extra board to fill in he could use douglas fir. You should try to get as dry as possible. Look at the end of the board and count the growth rings and the angle of the rings. Strive for as many ring per inch as you can, at least 8 per inch, and the ring slant of no more than 45 degrees if you are

using the board in a longeron. When you buy a board from the lumber yard a 1" X 4" actually measure about 3/4" X 3 3/4". Be sure its a full 3/4" thick if you are using it in your 3/4" thick structure. You of course will be buying No#1 grade clear stock.

Other wood can also be substituted in some areas. A softer pine can be used in the fuselage corner blocks that tie in the rib to spar junctures. I laminated some pine strips in my windshield-canopy bows. You should never use a soft wood in high stress areas like the longerons, spar caps, through bolt areas, etc. Let's say you need a 3/4" X 1 1/4" piece of spruce and you find you have a 3/4 X 1" in your scrap pile. There is nothing wrong in laminating a strip onto your 3/4 X 1" to fill it out to the correct width. Lets say you need a 3/4 X 1" board 7 foot long, but you only have two pieces 3/4 X 1" X 4 foot long. You can make a 10 to 1 scarf joint to get the board you need. Cut your two 3/4" X 1" boards on an angle 10" long and glue the two together into one long piece. It is important to note that I only advocate a scarf where a ply skin will cover the scarf!!

A local GP-4 builder called saying he cut his canopy base a bit under size. As you all know this 1/2" aircraft ply is very expensive. I told him to cut a thin batten of spruce and laminate it around the perimeter then reshape as necessary. I went over to his shop to see the results. He did a beautiful job. In fact I have never seen better wood work. He should end up with a beautiful GP-4 if this quality workmanship continues.

Our fall weather here in northern California is a beautiful time to fly. I have made several demo flights recently where the air is clear and stable. The right seat has 3" rudder pedal extensions that flip up or down. On one of those recent flights my passenger had one pedal extended and the other one not extended. He ended up buying the plans but remarked "Boy you sure have to hold a lot of right rudder". Who says you can't win'em all!

Regards

George



EDITORS CORNER

My, how time fly's! This is our fifth and last issue of 1995. The current subscriber bases is at 111 and continues to grow almost weekly.

The GP-4 builder.....I've had the opportunity to talk or read letters from quite a few of the builders. The enthusiasm for the GP-4 is quite overwhelming. I've learned a lot about the GP-4 builder, he is a different "bread of cat". He or she (yes, we have a she!) walks to the beat of their own drum, no one else's. They know exactly what they want, they don't care what everybody else is doing. And they are very, very tenacious. They break down their GP-4 project into 20 or so sub-assemblies and charge ahead, slowly but surely. Most are not on a time schedule, when it's done.....it's done. Almost every GP-4 builder that will finish their plane is a craftsman at heart. They are building to "build" first and the flying part is secondary, but they know their completed GP-4 will be their reward. A GP-4 builder is a person that is building an airplane that they have full intentions in keeping. I've enjoyed working with all of the GP-4 builders and George Pereira in 1995 and look forward to 1996.

We need to stick together..... Everyone's renewal is now due for 1996 (see page 7 for details). We have 111 subscribers currently on the roster and we need this many people as subscribers to make sense of doing the newsletter and to keep us supplied with input. The newsletter has grown in content, but I know it hasn't grown passed 8 pages. I have been very concerned on how this has been received by the group in that our original goals where to average 12 pages per issue. I have asked some of you for input on this subject. Quite a few of you have been very kind in saying that there is more information packed into the 8 pages of the GP-4 newsletter than some other newsletters have in 3 issues of theirs. I feel that the newsletter and the group will grow in size and content as more builders get deeper into their projects.

Newsletter input..... I would first like to thank George for his input to the newsletter. I have found his words priceless and learn something with every one of his articles. George, thanks for sharing your knowledge and thank you for the GP-4 it's self. OK now you other "Scoundrels", Yes you! We have gotten some excellent input to the newsletter and we have some excellent info coming up in the next issue. BUT..... we have quite a few of you guys that are "sitting on you thumbs". Everyone should have something to offer, even if they haven't necessarily started on the GP-4. We have people out there that welders, skilled wood craftsmen,

engineers, painters and etc. We have people that are full time general aviation A & P's and I & A's. You need think about what you have to offer. Things that you take for granted day in and day out, some other builder may not have a clue about. You A & P's and I & A's you could be keeping us abreast of all the thing we need to know about the 200 HP IO-360 Lycoming we use, like AD's & SDR's, used engines, misc. parts. You welders, you should be able to tell us about some welding techniques. How about you wood guys.....come on! There is a couple of people that have made jigs to turn their wing and one gentleman built a metal jig to rotate his entire assembled GP-4 nose first so he could paint his plane. Where are those pictures and articles to go with. Come on people share those experiences with the rest of the group! We would also like to hear your suggestions and ideas for the newsletter. All input is welcomed

1996 activities.....Is there interest in having builders forums at Sun N' Fun and Oshkosh for the GP-4 group this coming year. We also could arrange to have builders dinners also! Please let George or myself know of your thoughts soon as you can so we can plan accordingly.

WE HAVE A STAR!


● Darry Capps goes Hollywood!

I was watching ESPN a couple weeks back and they had an one hour show about the big Oshkosh fly-in. It was an excellent presentation of the event.

Partially the way through the show they reported on the Denver to Oshkosh race. And then before you know it there's the very modest Darry Capps telling them on how the race went.

Now we are just going have to call Darry "HOLLYWOOD" from now on! I just wonder how many people saw this show and said what to hell is a GP-4. Thanks for the exposure Darry...I mean Hollywood!

For those of you that missed that show I believe that video is available from the EAA. It just might be the same thing as their annual 1996 Oshkosh video. I'll try and find out more about it before the next newsletter. -- Spud



RENEWAL FOR 1996

Everyone's subscription is now due for 1996.

Subscription fee for 1996 for six issues will be as follows:

Inside the U.S. \$18.00
Canada & Alaska \$20.00 U.S Funds
Overseas \$29.00 U.S Funds

Personal checks made out to Bill Spornitz OK for U.S subscribers only. All other must be a money order or cash.

Mail your remittance to:

Bill Spornitz
1112 Layton Drive
Olathe, KS 66061
(913)764-5118

THE CLASSIFIEDS

For Sale: INSTRUMENT PANEL LAYOUT STICKERS- Trying to lay out your instrument panel and you've forgotten which circle is which? Here's what you need!! A packet of 10 pages of full size photo-repro's of instruments, gauges, switches, etc. Just peel them off and stick them to a mockup of the panel or on the instrument panel itself. A good way to fly the instruments before the plane is finished. Send \$20.00+\$2.50 S/H to Houde Enterprises, 12573 U.S. HWY 26, Riverton, WY 82501

For Sale: Pre-fabricated composite components for GP-4. Cowling - \$700.00, exhaust blisters - \$100.00, inlet ramps - \$100.00, tailcone - \$100.00. All four peices for \$925.00. Jake Jackson - Rio Linda, CA (916) 992-0608

For Sale: Elevator torque tube as per DWG 12 and rudder pedals and clivis arms per DWG 7 \$150.00 Don Milker, Port Ludlow, Washington (360)437-9331

DON'T FORGET TO RENEW YOUR SUBSCRIPTION!

Subscribers Information Center

GP-4 Builders & Flyers Newsletter (GP4BFN) is currently published Bimonthly at a rate of \$3.00 per issue/\$18.00 a year in U.S. \$3.33 per issue/\$20.00 a yr. in Canada, Alaska & Mexico. \$4.83 per issue/\$29.00 a yr. (U.S. funds) per 6 issues to foreign subscribers. Send remittance to: GP4BFN, 1112 Layton Drive, Olathe, Kansas 66061. **PLEASE MAKE CHECKS PAYABLE TO: BILL SPORNITZ**

Ideas and opinions expressed in GP4BFN are solely those of the individual submitter. This information is for educational purposes only! Application of these ideas and/or suggestions contained in GP4BFN are the sole responsibility of the experimental aircraft builder at their own risk, which could result in builder/pilot personal injury or death. GP4BFN, George Pereira, Osprey Aircraft do not imply or suggest in any way their usage.

Letters, Pictures and computer supplied data submitted to GP4BFN are subject to final screening by GP4BFN / Bill "Spud" Spornitz and may be restricted, deleted or revised. Material returned by request only.

Classified advertising; (non-commercial) for current subscribers may place an ad of 50 words or less for \$6.00 per issue, with one photo an additional \$14.00. Back issues of "GP-4 Builders & Flyers Newsletter", back issues are available for \$3.00 each.

The use of "Lycoming", "Hartzell" and/or "Osprey Aircraft" by GP4BFN is for the sole purpose of application and description only and is not intended to infer or imply a direct connection between GP4BFN, Lycoming, Hartzell or Osprey Aircraft.

913-764-5118

E-MAIL BSPORNITZ@AOL.COM

*MERRY CHRISTMAS
AND
HAPPY NEW
YEAR!*



1112 LAYTON DRIVE
OLATHE, KANSAS 66061

FIRST CLASS MAIL

**THIS IS YOUR LAST ISSUE FOR 1996!
PLEASE RENEW! SEE PAGE 7 FOR DETAILS**